DRIVER UTILITY    SR-5960RX-R2N (BPC-8960) v2.0

=======================================================================
======

  1. Click on the self-extracting and self-installing setup file and
     answer all prompts presented.


  2. You will be prompted to reboot when installation is complete.
-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-
  DRIVER CD CONTENT (omron)
-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-
   DRIVER\
                |
                |
                +--->\Chipsets\infinst_autol.exe (for Intel(R) Chipset Device Software

Installation Utility)
                |
                |
                +--->\LAN\--+--\PROWin32.exe    (for Intel 82567V-3 GIGA-LAN Driver)
                |
                |
                +--->\SOUND\--+-->32bit_Vista_Win7_R265 (for Realtek ALC888 Audio

Driver)
                |
                |
                +--->\VGA\--+--\Win7.exe (for Intel(R) Graphics Media Accelerator 3150

VGA driver)



MANUAL\Adobe\AdbeRdr930_en_US.exe (PDF File reader)



=======================================================================

========

1. The Intel(R) Chipset Device Software, You will find the contents of the directory in the UTILITY.

     OS support : Windows XP/Vista/Win7

2. The system has LAN function (Intel 82567V-3) that can support various network adapters,
     You will find the contents of the directory in the LAN.

     OS support : Windows XP/Vista/Win7

3. The Realtek AlC888 High Definition sound function enhanced in this system fully compatible with
     Windows XP/Win7, You will find the contents of the directory in the SOUND.

     OS support : Windows XP/Vista/Win7

4. The VGA interface (Intel Graphics Media Accelerator 3150) Build-in Intel Pineview D.
     you will find the content of the VGA directory.

     OS support : Windows XP/Vista/Win7

** Third party trademarks or brand names are the property of their owners.**

=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-

Release Note:
The driver version from v1.0 updated to v2.0, update all new drivers.
S8960 G1B modified:
1. DDR2 changes to DDR3.
2. DVI-D to DVI-I solution.
3. N455 co-lay circuit removed.
4. IRDA material modified.
5. AHCI item removed from BIOS.

=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-=-

=-=-=-=-=-=-

SR-5960RX-R2N Version info:

BIOS:89602P04.bin

Win7/Chipset:ReleaseNotes_9.2.0.1030

Win7/LAN:16.6

Win7/SOUND:R265

Win7/VGA:Graphics(8.14.10.2230)