


Driver DVD Revision History

20210525--> Add Win10-2019 driver

20220722--> Update Intel Graphics Driver 30.0.101.1994

DRIVER DISC content

Layer 1	
\API Package	Folder
\DRIVER	Folder
\USER MANUAL	Folder
README	PDF file



Layer 2 \API Package folder	
\DEMO PROJECT folder	Demo AP
\Prox API Standard folder	API
\Document folder	Guide

Layer 2 \DRIVER folder											
\Flash BIOS folder	BIOS & Updating tool										
\Platform folder	<p>Driver</p> <ol style="list-style-type: none"> The sequence of setup is, Main Chip => Hotfix => Graphics => Serial IO => Intel(R) TXE Package => LAN Chip => Sound Codec You will be prompted to reboot when installation is complete. <p>Main Chip /Intel® Apollo Lake</p> <table border="1"> <tbody> <tr> <td rowspan="2">Windows 10 IOT Enterprise</td> <td>32bit</td> <td>NA</td> </tr> <tr> <td>64bit</td> <td>10.1.1.38</td> </tr> <tr> <td rowspan="2">Windows 10 LTSC(2019)</td> <td>32bit</td> <td>NA</td> </tr> <tr> <td>64bit</td> <td>10.1.17968.8131</td> </tr> </tbody> </table>	Windows 10 IOT Enterprise	32bit	NA	64bit	10.1.1.38	Windows 10 LTSC(2019)	32bit	NA	64bit	10.1.17968.8131
Windows 10 IOT Enterprise	32bit		NA								
	64bit	10.1.1.38									
Windows 10 LTSC(2019)	32bit	NA									
	64bit	10.1.17968.8131									

\Platform folder

Hotfix / Windows10 critical security update

Windows 10 IOT Enterprise(2016)	32bit	NA
	64bit	kb3211320 kb3213986

Graphics /Intel®HD

Windows 10 IOT Enterprise	32bit	NA
	64bit	21.20.16.4590
Windows 10 LTSC(2019)	32bit	NA
	64bit	30.0.101.1994

Serial IO /

Windows 10 IOT Enterprise	32bit	NA
	64bit	30.100.1631.3
Windows 10 LTSC(2019)	32bit	NA
	64bit	30.100.1631.3

Intel® TXE Package

Windows 10 IOT Enterprise	32bit	NA
	64bit	3.0.0.1115
Windows 10 LTSC(2019)	32bit	NA
	64bit	APL-M 3.1.60.2280 APL-I 3.1.65.2288

LAN Chip/ INTEL I210

Windows 10 IOT Enterprise	32bit	NA
	64bit	12.15.184.0
Windows 10 LTSC(2019)	32bit	NA
	64bit	12.15.184.1

Sound Codec / Realtek ALC888S

Windows 10 IOT Enterprise	32bit	NA
	64bit	6.0.1.8036
Windows 10 LTSC(2019)	32bit	NA
	64bit	6.0.1.8186

Layer 2 \DRIVER folder

\Device folder

Touch / eGalax Touch

Main board version		
Windows 10 IOT Enterprise	32bit	NA
	64bit	5.14.0.14916

WIFI module/ AJ-RTL-8812AEACC-01

for Windows10	32bit	3.00.0012
	64bit	3.00.0012
for Linux		
	64bit	V5.1.5

WIFI module/ ZQ802XRN7-01

for Windows10	32bit	NA
	64bit	2013.7.901.2014

4G / EC25-E

for Windows10	32bit	V1.0
	64bit	V1.0
for Linux	32bit	V1.3.0
	64bit	

4G/ MPC1-L210

for Windows10	32bit	V1.0.1.6
	64bit	V1.0.1.6